#### Page

#### AGENDA

#### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

HEARING COMPUTER SCHEDULED

CASE NO: CE03062271 CASE ADDR: 110 SW 3 AV

#111 PROPERTIES INC OWNER: INSPECTOR: THOMAS CLEMENTS

VIOLATIONS: NFPA 10 4-4.1

FIRE EXTINGUISHER IS PAST DUE FOR ANNUAL CERTIFICATION.

NFPA 1 6-1.5

EXTENSION CORDS ARE BEING USED AS PERMANENT WIRING.

NFPA 1 1-4.5

MAXIMUM CAPACITY SIGN IS NOT POSTED.

CASE NO: CE03070354
CASE ADDR: 3101 SW 12 PL
OWNER: TONES WIRES

JONES-MURRAY, BERBETH & MURRAY, GLENN

INSPECTOR: THOMAS CLEMENTS

VIOLATIONS: NFPA 1 6-1.2

THE EXIT LIGHTS ARE IMPROPERLY WIRED.

NFPA 101 26.3.3.1

THERE IS NO FIRE ALARM SYSTEM PROVIDED.

NFPA 101 7.9.1.1

EMERGENCY LIGHTING IS NOT PROVIDED.

NFPA 101 26.2.3

THE MIMINUM CLEAR WIDTH OF DOOR OPENING INTO BATHROOM IS NOT

PROVIDED.

NFPA 101 26.3.5.2

AN AUTOMATIC FIRE SPRINKLER SYSTEM IS NOT PROVIDED.

NFPA 1 13-1.1

A RANGE HOOD SYSTEM CONSISTENT WITH NFPA 96 IS NOT PROVIDED.

\_\_\_\_\_\_

RETURN HEARING (OLD BUSINESS)

CASE NO: CE02101544

CASE ADDR: 2933 POINSETTIA ST \*\*REOUEST FOR EXTENSION OF TIME\*\*

GATOR EAST WIND PARTNERS OWNER:

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

THERE HAVE BEEN IMPROVEMENTS TO THIS PROPERTY THAT HAVE BEEN DONE WITHOUT PERMITS, THAT INCLUDE BUT ARE NOT LIMITED TO:

- (1) BUILT AN IN GROUND FOUNTAIN POOL WITH A BRICK PAVER PATHWAY.
- (2) ENCLOSED ELEVATOR SHAFT.
- (3) ENCLOSED STAIRWAY.
- (4) ADDED A ROOF TOP APARTMENT.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003 10:00AM

FBC 104.2.11

INSTALLED A WALL AIR CONDITIONING UNIT IN THE ROOF TOP APARTMENT WITHOUT A PERMIT.

FBC 104.2.4

ADDED PLUMBING WITHOUT PERMITS THAT INCLUDE BUT ARE NOT LIMITED TO:

- (1) PLUMBING FOR THE POOL FOUTAIN.
- (2) PLUMBING FOR THE ROOF TOP APARTMENT.

FBC 104.2.5

ADDED ELECTRICAL WITHOUT PERMITS THAT INCLUDE BUT IS NOT LIMITED TO:

- (1) ELECTRICAL FOR THE POOL FOUNTAIN.
- (2) ELECTRICAL FOR THE ROOF APARTMENT.

FBC 1015.1

THERE IS NO GUARDRAIL AROUND THE PERIMETER OF THE ROOF WHERE THE ROOF TOP APARTMENT IS LOCATED.

\_\_\_\_\_\_

#### HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE03061307
CASE ADDR: 2140 NW 6 ST
OWNER: SEEL,STACY

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

POURED CONCRETE FOR SLABS AT THIS CAR WASH, INSTALLED CAR TENTS, ALTERED THE INTERIOR OF THIS BUILDING, ALL WITHOUT PERMITS.

FBC 11-4.6.1

THERE ARE NO ACCESSIBLE PARKING SPACES, OR STRIPPING FOR THIS PROPERTY.

FBC 104.2.11

INSTALLED TWO (2) AIR CONDITIONING UNITS WITHOUT A PERMIT AND NOT PER CODE.

FMC 403.3

THERE IS NO MECHANICAL VENTILATION OR WINDOW IN THIS TOILET ROOM.

FPC 403.1

THERE IS NO SINK IN THE TOILET ROOM OF THIS CAR WASH BUSINESS.

FBC 1820.3.

WIRE MESH WAS NOT INCLUDED PRIOR TO THE POURING OF THE CONCRETE SLABS.

47-25.3 A.3.d.

THERE IS NO BUFFERYARD WALL ON THIS COMMERCIAL PROPERTY ABUTTING THE RESIDENTIAL AREA IN THE REAR.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003 10:00AM

47-21.9 G.1.

THERE IS NO RETROACTIVE VIA LANDSCAPING AT THIS CAR WASH PROPERTY.

\_\_\_\_\_\_

#### RETURN HEARING (OLD BUSINESS)

\_\_\_\_\_

CASE NO: CE00080137

CASE ADDR: 3001 STATE ROAD 84
OWNER: NEW RIVER BOAT CLUB INC
INSPECTOR: WAYNE STRAWN

VIOLATIONS: 15-28

THE NEW RIVER MARINA IS NOT OPERATING WITH A CURRENT OCCUPATIONAL LICENSE.

2309.1(c)

STRUCTURES WHICH HAVE BEEN BUILT ON THE PROPERTY, INCLUDING, BUT NOT LIMITED TO, GUARD HOUSE, DOCKMASTER SHACK, LEAN-TO SHELTERS, WORKSHOP ON NORTH OF PROPERTY, DOCKS AND STORAGE SHEDS HAVE NOT BEEN DESIGNED TO PREVENT UPLIFT AS REQUIRED.

2315.1(a)

THE ENCLOSING WALLS FOR THE WORKSHOPS ON THE GROUND FLOOR OF THE MAIN BUILDING ALONG WITH OTHER ACCESSORY STRUCTURES ON THE PROPERTY HAVE NOT BEEN DESIGNED TO WITHSTAND THE IMPACT REQUIREMENTS OF THE CODE.

301(a)

EXTENSIVE CONSTRUCTION AND ALTERATION WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO THE ERECTION OF A LARGE MEMBRANE STRUCTURE, SEAWALL CONSTRUCTION, REPAIR AND/OR ALTERATIONS, THE CONSTRUCTION OF ACCESSORY STRUCTURES INCLUDING A GUARD HOUSE, STORAGE SHEDS, DOCK MATSTER SHACK (HEXAGONAL), LEAN-TO SHELTERS FOR THE PROTECTION OF WORKMEN, A WORKSHOP ON THE NORTH END OF THE PROPERTY, EXTENSIVE REPLACEMENT OF DOCKS, THE MOVE IN OF TRAILERS FOR STORAGE AND OFFICES, FENCING, A SIGN STRUCTURE AND THE ENCLOSURE OF AREAS ON THE EAST AND WEST SIDE OF THE MAIN BUILDING (FIRST FLOOR) FOR USE AS WORKSHOPS.

3806.2(c)

THE REQUIRED FIRE PROTECTION ACCORDING TO NFPA 303 IS NOT BEING PROVIDED.

4501.2(d)

LACK OF PROPER MAINTENANCE AND EXTENSIVE ALTERATIONS CONTRARY TO THE REQUIREMENTS OF THE NATIONAL ELECTRIC CODE HAVE RESULTED IN UNSAFE ELECTRICAL CONDITIONS IN THE MARINA.

4505.1(a)

EXTENSIVE ALTERATIONS, EXPANSIONS AND REPAIRS TO THE ELECTRICAL SYSTEM OF THE MARINA HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES BUT IS NOT LIMITED TO CIRCUITRY FOR DOCK POWER, EQUIPMENT POWER, ACCESSORY BUILDING POWER AND POWER FOR SIGNS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

4603.21(a)

TEMPORARY TOILET FACILITIES HAVE BEEN SET UP WITHOUT THE REOUIRED APPROVALS.

47-20.20 D.

THE PARKING FACILITIES ARE BEING UTILIZED FOR THE STORAGE OF BOATS WHICH IS PROHIBITED.

47-22.9.

SIGNS HAVE BEEN ERECTED ON THE PROPERTY WITHOUT OBTAINING THE REOUIRED PERMITS.

47-34.1 A.1.

BOATS ARE BEING STORED ON THE V.U.A. LANDSCAPING WHICH IS PROHIBITED ACCORDING TO THE PROTECTION REQUIREMENTS AT 47-21.9.B.4..

#### HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE03020099 CASE ADDR: 812 NW 8 AVE

OWNER. LEONARDI, ANTHONY TR & LEONARDI INVESTMENT TRUST

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 15-28

THE BUSINESS BEING OPERATED AT THIS LOCATION IS NOT OPER-ATING WITH A CURRENT OCCUPATIONAL LICENSE.

47-22 9

SIGNAGE HAS BEEN PAINTED ON THE WALL WITHOUT OBTAINING THE REOUIRED PERMITS.

FBC 104.1

AUTOMOBILE LIFTING APPARATUS HAS BEEN INSTALLED IN THE BUILDING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 104.2.11

AIR CONDITIONING HAS BEEN INSTALLED IN THE OFFICE AREA WITH-OUT OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

CIRCUITS HAVE BEEN ADDED TO POWER GARAGE LIFTS AND LIGHTING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED IN A SAFE CONDITION.

- 1. THE ELECTRICAL SYSTEM HAS LOOSE CONDUIT, EXPOSED WIRES AND CIRCUITS ADDED WITHOUT OBTAINING PERMITS.
- 2. THE BUILDING IS BEING UTILIZED FOR AUTOMOBILE STORAGE AND REPAIRS WITHOUT HAVING THE REQUIRED VENTILATION.
- 3. A COMPRESSED AIR SYSTEM HAS BEEN INSTALLED WITHOUT OBTAINING PERMITS AND UTILIZING PLASTIC PIPING WHICH IS PROHIBITED BY 303.2 (FBC, P)

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

#### FBC,M 401.2

AUTOMOBILES ARE BEING STORED INSIDE THE BUILDING WITHOUT THE REQUIRED VENTILATION AS SPECIFIED BY 403.3.

CE03022088 CASE NO: CASE ADDR: 3623 DAVIE BLVD OWNER:

GLASTON, H & MINERVA L

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-25.3 A.3.d.iv.

THE REOUIRED PHYSICAL BARRIER FOR THE PURPOSE OF A BUFFER BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

#### FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT OBTAINING THE RE-QUIRED PERMITS; ROOF RAFTERS ON THE NORTHEAST CORNER OF THE ROOF AT 3623 HAVE BEEN REPAIRED, A SHORT WALL CONSTRUCTED ON THE EAST END OF THE BUILDING DESIGNED TO PREVENT ACCESS TO THE ALLEY BETWEEN BUILDINGS AND AN AWNING STRUCTURE ATTACHED TO THE REAR OF 3623.

#### FBC 104.2.11

VENTILATION WORK HAS BEEN DONE WITHOUT OBTAINING THE RE-OUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A FAN INSTALLED AT THE REAR OF 3625 (GATOR TINT) AND AN AIR CONDITIONING UNIT INSTALLED AT THE REAR OF 3623.

#### FBC 104.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: WASTE PIPING ON THE REAR EXTERIOR WALL OF 3635 WHICH DRAINS OUT ON THE GROUND, AND NEW SUPPLY PIPING ON THE REAR WALL OF 3625 (GATOR TINT).

#### FBC 104.2.5

CIRCUITS HAVE BEEN ADDED TO THE EXISTING BUILDINGS ELEC-TRICAL SYSTEM WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A CIRCUIT FOR A FAN AT THE REAR OF 3635 AND A CIRCUIT FOR AN OUTSIDE LIGHT AT THE REAR OF 3635.

#### FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED IN A SAFE CONDITION BY REASON OF WORK DONE WITHOUT PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: IMPROPER ROOF REPAIRS AND UNSAFE AWNING STRUCTURE (REAR) AT 3623 AND A SHORT WALL CONNECTING THIS BUILDING TO THE ADJOINING BUILDING ON THE EAST.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

CASE NO: CE03032479 CASE ADDR: 729 NW 7 TER

OWNER: ROY, DAVID & JIWANI RADHICA

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.1

A NEW GARAGE DOOR HAS BEEN INSTALLED WITHOUT OBTAINING A

PERMIT.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE02080290

\*\*REQUEST FOR EXTENSION OF TIME\*\* CASE ADDR: 416 N FEDERAL HWY

OWNER: MAYHU CORP INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 15-28

ENGAGING IN BUSINESS WITHOUT FIRST OBTAINING AN

OCCUPATIONAL LICENSE.

47-19.9

THERE IS OUTDOOR SALES, STORAGE, DISPLAY OF GOODS, WHICH

IS NOT IN COMPLIANCE WITH CODE.

47-20.8

PARKING LOT NEEDS RESTRIPING.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT. THIS INCLUDES:

1-BUILT WOOD DECK AND TIKIHUT IN PARKING AREA (NOTE: APPLIED FOR PERMIT #02090054, BUT FAILED

ZONING ON 10/22/02) 2-INSTALLED SIGNAGE

3-INSTALLED FOUNTAIN WITHOUT PERMIT

4-NEW DOOR/SHUTTER ON THE SOUTH SIDE OF PROPERTY

FBC 11-4.6.4

THE REQUIRED HANDICAP SIGNAGE FOR THE EXISTING BUILDING

IS NOT IN COMPLIANCE WITH CODE.

\_\_\_\_\_\_

HEARING COMPUTER SCHEDULED

CASE NO: CE01100240 CASE ADDR: 631 NE 18 AV
OWNER: STORELLI, JOHN & SUSAN

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

ENCLOSED CARPORT WITHOUT OBTAINING REQUIRED PERMITS.

NOTE: BOARD OF ADJUSTMENT CASE NO 01-47 APPEAL DENIED

PERMIT APPLICATION A-0105283 FAILED ZONING.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE02120345

3232 SW 2 AV # 107 CASE ADDR: OWNER: SMITH, STEVEN M INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT TO INCLUDE:

1. ADDITION OF NEW OFFICE, WHICH INCLUDES, STRUCTURAL WOOD COLUMN, BEAMS, STAIRS AND NEW 2ND FLOOR.

FBC 104.2.5

NEW ELECTRICAL WORK, IN TWO-STORY OFFICE WITHOUT FIRST

OBTAINING REQUIRED PERMITS.

CASE NO: CE03010838 CASE ADDR: 720 NE 18 AV
OWNER: SHARP, FLORENCE KENDALL

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MIT.

1. INSTALLED NEW SHED IN BACKYARD

CASE NO: CE03041498

1135 N FEDERAL HWY PMG PLAZA INC CASE ADDR: OWNER: INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. INSTALLED NEW EXTERIOR DOOR

2. INSTALLED NEW SIGNS

3. NEW INTERIOR WALLS AND DOORS

CASE NO: CE03042289
CASE ADDR: 1221 NE 3 AVE
OWNER: TITANS OF FORT LAUDERDALE LLC

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE

BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

- 1. NEW EXTERIOR DOORS
  - 2. NEW WINDOWS
  - 3. NEW KITCHEN CABINETS

  - 4. NEW FENCE 5. NEW SIDING

#### FBC 104.2.4

NEW PLUMBING WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. PLUMBING IN KITCHEN
- 2. NEW EXTERIOR COPPER PIPING WITH VALVES

#### FBC 104.2.5

NEW ELECTRICAL WORK, WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. NEW LIGHT FIXTURES

\_\_\_\_\_\_

CASE NO: CE03051896 CASE ADDR: 5470 NW 10 TER
OWNER: DENMAN LIMITED L L C

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.2.4

NEW AIR CONDITIONING ADDED IN OFFICE ROOMS BUILT WITHOUT FIRST OBTAINING REQUIRED PERMITS.

#### FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS, THIS INCLUDES:

- 1. ADDED STAIRS AND LOFT IN THE WAREHOUSE
- 2. NEW ROOMS ADDED (COMPLETE NEW DOORS, WINDOWS, ELECTRICAL, AIR CONDITIONING) TO THE EXISTING OFFICE NORTH AND WEST SIDE OF WAREHOUSE
- 3. REPLACE ROLLING SHUTTER DOOR IN THE WEST SIDE OF WAREHOUSE
- 4. BUILT WOOD SHEETING WALL INSIDE OF END WALL ON THE EAST SIDE
- 5. ADDED NEW EXTERIOR DOOR ON THE WEST SIDE OF BUILDING

#### FBC 104.2.5

ELECTRICAL WORK IN OFFICE ROOM (NEW FIXTURES, NEW PANEL,

ETC) WAREHOUSE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 11-4.1.2(5)(a)

THERE IS NO HANDICAP PARKING.

#### FBC 11-4.6.4

THERE IS NO HANDICAP SIGNAGE.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003 10:00AM

47-20.20 H.

PARKING LOT IS IN DISREPAIR AND NEEDS REPAIR AND RESTRIPING.

9-306

EXTERIOR BUILDING NEEDS PAINTING.

9-305

LANDSCAPING NEEDS MAINTENANCE.

FBC 11-4.3

THERE IS NO ACCESSIBLE ROUTE (RAMP) FROM PARKING LOT TO BUILDING.

FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE:

- 1. EXIT LIGHTS NOT WORKING
- 2. EXTERIOR MULTIRIB PANELS ARE DAMAGE/RUSTED ALMOST ON ALL EXTERIOR WALLS NEED STRUCTURAL REPAIRS.
- 3. OVERHANG STEEL BEAM ON THE SOUTH SIDE OVER DOCK IS RUSTED NEEDS IMMEDIATE REPAIR.
- 4. STEEL BEAMS ATTACHED TO THE EAST END WALL ARE RUSTED AND STRUCTURALLY DAMAGED NEED IMMEDIATE REPAIR.
- 5. STEEL BEAM ON THE SOUTHWEST CORNER IS RUSTED AND IN NEED OF IMMEDIATE REPAIR.
- 6. STEEL COLUMNS AND THEIR ATTACHMENT BOLTS TO THE FLOOR IS RUSTED AND NEEDS REPAIR
- 7. DOCK STEM WALL DAMAGED ON THE WEST SIDE, NEEDS REPAIRS
- 8. EXHAUST FANS NOT WORKING
- 9. ELECTRICAL PANEL AND GUTTER MISSING COVER, WIRES HANGING, UNSAFE CONDITION, NEED COMPLETE CHECK-UP AND A LETTER FROM AN ENGINEER ABOUT ITS SAFETY
- 10. ELECTRICAL LIGHTS NOT WORKING IN OFFICE AND WAREHOUSE

\_\_\_\_\_\_

# RETURN HEARING (OLD BUSINESS)

-----

CASE NO: CE02071382
CASE ADDR: 231 SW 8 AVE
OWNER: HAAN, NOLAN
INSPECTOR: KENNETH REARDON

\*\*REQUEST FOR THE EXTENSION OF TIME\*\*

VIOLATIONS: FBC 104.9.3.1 \*Complied\*

THE PERMITS TO RELOCATE AND REMODEL THIS BUILDING HAVE EXPIRED SINCE NO PASSING INSPECTIONS WERE OBTAINED IN OVER 90 DAYS.

FBC 106.1

THIS BUILDING IS BEING OCCUPIED WITHOUT FIRST OBTAINING A CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

#### CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE02100344
CASE ADDR: 1430 SW 34 TER
OWNER: STEWART,NORMAN
INSPECTOR: KENNETH REARDON

\*\*REQUEST FOR EXTENSION OF TIME\*\*

VIOLATIONS: 9-280(q) Complied

THE EXTERIOR ELECTRICAL IS NOT MAINTAINED AND THERE IS LOOSE AND EXPOSED WIRED AND FIXTURES.

#### 9-281(b) **Complied**

THE YARD IS NOT BEING MAINTAINED. THE GRASS IS OVERGROWN IN AREAS AND MISSING IN OTHER AREAS. THERE IS TRASH, RUBBISH AND DEBRIS THROUGHOUT THE YARD, INCLUDING, BUT NOT LIMITED TO THE FOLLOWING:

1-AN OLD AIR CONDITIONING UNIT

2-AN OLD GAS FURNACE

3-OLD PVC PIPING

4-ABANDONED FENCING

5-OLD AIR CONDITIONING FREON GAS LINES

6-BROKEN UP CONCRETE

7-AN OLD TOILET

8-FRONT YARD SAND PILE

#### FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT

- 1- THE BUILDING HAS BEEN REROOFED.
- 2- INTERIOR DRYWALL WORK
- 3- KITCHEN AND BATHROOM CABINETS HAVE BEEN REMOVED
- 4- WINDOW REPLACEMENT
- 5- EXTERIOR STUCCO WORK

# FBC 104.2.4 Complied

THE DEMOLITION OF THE KITCHEN, BATHROOM AND WATER HEATER PLUMBING WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

# FBC 104.2.5 Complied

THE INTERIOR ELECTRIC FIXTURES HAVE BEEN REMOVED AND CIRCUITS ADDED TO THE REAR AND SOUTH EXTERIOR WALLS WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

#### FBC 3401.6 Complied

THERE ARE LARGE STRUCTURAL CRACKS ON T5HE NORTH AND EAST EXTERIOR WALLS.

-----

CASE NO: CE03021896
CASE ADDR: 800 SW 22 TER
OWNER: VEGA, GLORIA S
INSPECTOR: KENNETH REARDON

\*\*REQUEST FOR EXTENSION OF TIME\*\*

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

ENCLOSING THE CARPORT INSTALLED SECURITY BARS OVER THE WINDOWS INSTALLED TWO LARGE RADIO ANTENNA TOWERS

# 9-280(b) **Complied**

THE REAR SCREEN ENCLOSURE HAS TORN AND MISSING SCREENS.

#### 9-280(d)

THE REAR SHED IS IN POOR CONDITION AND HAS BEEN INSTALLED WITHOUT A PERMIT AND NEEDS TO BE REMOVED.

#### 9-305(b) Complied

THE YARD IS OVERGROWN IN AREAS AND HAS MISSING LIVING GROUND COVER IN OTHER AREAS.

# FBC 1005.5

THE SECURITY BAR DO NOT HAVE THE NECESSARY EMERGENCY ESCAPE AND RESCUE OPENING DEVICES.

\_\_\_\_\_\_

#### HEARING COMPUTER SCHEDULED

CASE NO: CE02101072 CASE ADDR: 5780 NW 9 AV MINK, JOHN P REV TR

INSPECTOR: KENNETH REARDON

#### VIOLATIONS: 18-27(a)

THERE IS OUTSIDE STORAGE BEHIND THE NORTHWEST OFFICE BUILDING INCLUDING, BUT NOT LIMITED TO FOUR UNLICENSED VEHICLES, OLD TUB, WHEELBARROWS, TIRES, SCAFFOLDING PIECES ALONG WITH TRASH, RUBBISH AND DEBRIS. THERE IS ONE UNLIC-ENSED VEHICLE, AN UNLICENSED TRAILER, BOXES AND SPOOLS OF RUBBER STRIPPING BEHIND THE SOUTHEAST WAREHOUSE BUILDING.

#### 47-22.3 R.

THE SANDWICH BOARD SIGN ON THE SIDEWALK IS ILLEGAL.

#### 47-22.3 S.

ILLEGAL WALL SIGNS HAVE BEEN ADDED TO THE BUILDING WITHOUT FIRST OBTAINING A BUILDING PERMIT.

#### 9-304(b)

THE PARKING AND ASPHALT AREAS ARE NOT BEING PROPERLY MAINTAINED AND STRIPPED.

#### 9-305(b)

THE GRAVEL AREA BEHIND THE NORTHWEST OFFICE BUILDING IS IMPROPER. THIS AREA IS SHOWN ON THE PLANS AS A GRASS AREA. THE SWALE AREAS ARE NOT BEING MAINTAINED.

#### 9-306

THE PAINT ON ALL BUILDINGS IS NOT BEING MAINTAINED TO THE MINIMUM STANDARDS OF THIS CODE.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

FBC 104.1

THE FOLLOWING WORK WAS PERFORMED WITHOUT FIRST OBTAINING A BUILDING PERMIT:

THE RESTAURANT BUILDING - THE RESTAURANT HAS BEEN EX-PANDED, MOVING INTO AN ADDITIONAL BAY, WHICH IS NOT SHOWN ON THE LATEST REMODELING PLANS FROM 1990 ON FILE WITH THE BUILDING DEPARTMENT. THE SUITE 5788 HAS THE REAR WALL OPENED UP TO ACCOMMODATE A WALL AIR CONDITIONING UNIT.

THE NORTHWEST OFFICE BUILDING - THE REAR WALL HAS BEEN OPENED UP TO ACCOMMODATE AN OVERHEAD GARAGE DOOR AND A WALL AIR CONDITIONING UNIT.

THE SOUTHEAST WAREHOUSE BUILDING - THE REAR WALL HAS BEEN OPENED UP TO ACCOMMODATE A WALL AIR CONDITIONING UNIT AND WALL FAN. THE WEST WALL HAS BEEN OPENED UP TO ACCOMMODATE A WALL AIR CONDITIONING UNIT. A DOOR HAS BEEN ADDED TO THE EAST WALL.

FBC 3401.6

THE RESTRAURANT BUILDING - THE CENTRAL AIR CONDITIONING SYSTEM DOES NOT FUNCTION IN SUITE 5788.

THE NORTHWEST OFFICE BUILDING - THE CENTRAL AIR CONDITIONING ROOF CONDENSER UNIT COVER IS MISSING.

THE NORTHEAST WAREHOUSE BUILDING - THERE ARE EXPOSED WIRES AT THE EXTERIOR WEST WALL PHOTOCELL.

THE SOUTHEAST WAREHOUSE BUILDING - THE CENTRAL AIR CONDITIONING ROOF CONDENSER UNIT COVER IS MISSING OVER THE BATHROOM OF ALL COAST PUMP AND MOTOR. THE METER ROOM DOOR IS ROTTED AND THE CEILING IS DAMAGED.

FBC 11-4.1.2(5)(a)

THERE IS NO HANDICAP PARKING.

FBC 11-4.6.2

THERE IS NO DEFINED ACCESSIBLE ROUTE OF TRAVEL FROM THE PARKING OT TO THE BUILDING.

FBC 1203.4.2

THERE IS NO VENTILATION IN THE BATHROOMS OF THE SOUTHEAST WAREHOUSE BUILDING ALL COAST PUMP AND MOTOR AND THE EXTERIOR BATHROOM NEXT TO THE METER ROOM.

-----

CASE NO: CE03020547 CASE ADDR: 414 SW 22 AV

OWNER: PATTERSON, CEDRIC L & LATONYA M

INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-313(b)

THE BUILDING NUMBERS ARE NOT POSTED ON THE HOUSE, AS REQUIRED.

FBC 104.1

GLASS BLOCK HAS BEEN INSTALLED IN TWO (2) WINDOW OPENINGS AND ONE (1) NEW WINDOW HAS BEEN INSTALLED WITH AN ALTERED OPENING, ALL ON THE NORTH WALL OF THE BUILDING.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03020870
CASE ADDR: 1340 SW 35 AV
OWNER: LOUIE, CORRINA Y TR
INSPECTOR: KENNETH REARDON

#### VIOLATIONS: FBC 104.1

THE FOLLOWING WORK WAS DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- 1. CUT THE TIE BEAM AND REPLACED A DOOR AT THE SOUTH SIDE OF THE CENTER BREEZEWAY.
- 2. APARTMENT A4 HAS BEEN ILLEGALLY CONVERTED INTO TWO (2) LIVING UNITS (A4 & A4A).
- 3. THE FRONT AND REAR WALLS HAVE BEEN OPENED TO ACCOM-MODATE WALL AIR CONDITIONING UNITS IN APARTMENTS A4 AND A4A.

#### FBC 104.2.4

PLUMBING LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL AND THE EXTERIOR WALL OF THE CENTER BREEZEWAY WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

#### FBC 104.2.5

ELECTRICAL LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL, THE EXTERIOR WALL OF THE CENTER BREEZEWAY AND TO THE WALL AIR CONDITIONING UNITS IN APARTMENT A4 AND A4A WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

#### FBC 104.2.11

WALL AIR CONDITIONING UNITS HAVE BEEN ADDED TO APARTMENTS A4 AND A4A WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

#### 9-279(f)

A PLUMBING WASTE LINE DISCHARGES TO THE GROUND AT THE REAR EXTERIOR WALL, JUST NORTH OF THE CENTER BREEZEWAY.

#### 9-280(f)

THERE IS A MISSING ROOF DRAIN PIPE AT THE NORTH END OF THE REAR WALL OF THE BUILDING, WHICH SHOULD BE REPLACED.

# 9-280(h)(1)

THE POOL WOOD AND CHAIN LINK FENCES ARE DAMAGED AND ARE NOT BEING MAINTAINED.

#### 9-280 (b)

THE RAIN GUTTERS ARE RUSTED AND DAMAGED. THERE ARE MISSING WINDOW SCREENS THROUGHOUT THE BUILDING. THE DOOR, DOOR FRAME AND WALL ARE ROTTED AT THE STORAGE AREA UNDER THE NORTH STAIRWAY.

# 9-304(b)

THE PARKING LOT HAS POTHOLES AND IS NOT BEING MAINTAINED TO THE MINIMUM STANDARDS OF THIS CODE.

# FBC 3401.6

THERE ARE STORED ITEMS IN THE METER ROOM. THIS IS NOT SAFE AND IS NOT ALLOWED.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003 10:00AM

9 - 305 (b)

THERE IS MISSING GRASS AT THE SOUTHWEST CORNER OF THE BUILDING.

47-19.4 D.8.

THE DUMPSTER ENCLOSURE FENCE WALLS ARE DAMAGED AND REQUIRE REPAIR.

.-----

CASE NO: CE03030636

CASE ADDR: 1009 MANDARIN ISLE
OWNER: WOLFNER, SANDRA CALKINS

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

BUILT A SCREEN ENCLOSURE AND INSTALLED A HOT TUB WITHOUT

FIRST OBTAINING A BUILDING PERMIT.

\_\_\_\_\_

CASE NO: CE03041279
CASE ADDR: 3133 SW 16 ST
OWNER: SMITH, ELINOR W
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE REAR AND WEST SIDE SCREEN PORCH AND THE CARPORT HAVE BEEN ENCLOSED WITHOUT FIRST OBTAINING A BUILDING PERMIT.

FBC 104.2.11

WALL AND WINDOW AIR CONDITIONING UNITS HAVE BEEN ADDED TO THE HOUSE WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

9-280(b)

THERE IS ROTTED WOOD AT THE CARPORT BEAMS, ROOF FASCIA BOARDS, ROOF OVER THE FRONT PORCH, AND AT THE WALL SIDING AROUND THE ILLEGALLY ENCLOSED REAR PORCH. THERE IS EVIDENCE OF A ROOF LEAK OVER THE FRONT PORCH.

FBC 3401.6

THERE IS AN EXTENSION CORD RUNNING FROM THE NEIGHBORING HOUSE TO THIS HOUSE TO PROVIDE POWER. THIS IS A MAJOR SAFETY HAZARD.

9-306

THE BUILDING PAINT IS NOT BEING MAINTAINED.

47-20.13 A.

THE DRIVEWAY IS DAMAGED, HAS POTHOLES AND MISSING ASPHALT AND IS NOT BEING MAINTAINED.

9-281 (b)

THERE IS A CAR AND A TRAILER ON THE PROPERTY THAT ARE UNLICENSED. THERE IS TRASH, RUBBISH, DEBRIS AND STORED ITEMS THROUGHOUT THE PROPERTY. THE YARD IS OVERGROWN AND NOT BEING MAINTAINED.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03050758 CASE ADDR: 2931 SW 14 ST

OWNER: LAMOUR, ELIKER D & STEPHAN INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

BUILT AN ADDITION TO THIS HOUSE FOR A BATHROOM, KITCHEN AND FLORIDA ROOM WITHOUT FIRST OBTAINING A BUILDING PERMIT. THE PERMIT WAS APPLIED FOR (PROCESS NUMBER 01070649) BUT

NEVER ISSUED.

FBC 104.2.4

INSTALLED PLUMBING IN THE NEW ADDITION WITHOUT FIRST

OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

INSTALLED ELECTRICAL IN THE NEW ADDITION WITHOUT FIRST

OBTAINING A PLUMBING PERMIT.

FBC 106.1

OCCUPIED ILLEGAL ADDITION WITHOUT FIRST OBTAINING A CERTIF-

ICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

CASE NO: CE03060737 CASE ADDR: 1150 SW 28 ST

A S G PROPERTIES INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING REMODELING HAS BEEN DONE WITHOUT FIRST OB-TAININTG A BUILDING PERMIT, INCLUDING, BUT NOT LIMITED TO NEW KITCHEN AND BATH CABINETS. THIS DUPLEX HAS BEEN CON-

VERTED INTO THREE LIVING UNITS.

FBC 104.2.4

THE BATH FIXTURES HAVE BEEN REPLACED WITHOUT FIRST OBTAINING

A PLUMBING PERMIT.

FBC 104.2.5

THE ELECTRICAL HAS BEEN UPDATED IN THE KITCHEN AND BATHROOMS

WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

CASE NO: CE02061228 CASE ADDR: 1225 NW 14 CT OWNER: BLYTHE, PAUL INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE

REQUIRED BYULDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF FENCE

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03021874 CASE ADDR: 1716 NW 8 PL OWNER: BLAKE, MOSES
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: 47-20.13 A.

PARKING AREA IS NOT BEING MAINTAINED.

47-21.8

GROUND COVER IS NOT BEING MAINTAINED AND HAS PATCHES OF BARE SAND.

6-34

THERE ARE MORE THAN THREE (3) DOGS BEING KEPT AT THIS LOCATION, WHICH CONSTITUTES A KENNEL.

9-278(q)

THERE ARE MISSING AND TORN SCREENS IN THE WINDOWS OF THIS LOCATION.

9-280(b)

THERE ARE DOORS AND WINDOWS WHICH ARE NOT WEATHER AND WATER TIGHT AND RODENT PROOF.

9-280(h)(1)

FENCE AT THIS LOCATION IS NOT BEING MAINTAINED AND HAS BROKEN, BENT OR MISSING SECTIONS.

9-306

WALLS ARE DIRTY AND PAINT IS CHIPPING AND PEELING ON BUILDING.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF CONCRETE PARKING AREAS
- B. INSTALLATION OF REPLACEMENT DOORS
- C. INSTALLATION OF CHAIN LINK FENCING
- D. INSTALLATION OF CONCRETE BLOCK WALLS

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR WOOD STRUCTURES INCLUDING SOFFITS, FASCIA AND ROOF.

CASE NO: CE03030070

CASE ADDR: 2158 NW 6 CT
OWNER: NEW LIFE CHRISTIAN FELLOWSHIP

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

A. INSTALLATION OF CHAIN LINK FENCING

B. INSTALLATION OF CANVAS CANOPIES.

CE03030470 CASE ADDR: 711 NW 4 ST

MT HERMON AFRICAN METHODIST EPISCOPAL CHURCH INC OWNER:

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF FENCE INTO ALLEY/RIGHT-OF-WAY

B. INSTALLATION OF SECURITY BARS

15-28

OPERATION OF A BUSINESS WITHOUT THE PROPER LICENSE.

\_\_\_\_\_\_

CASE NO: CE03031402 CASE ADDR: 201 NW 6 ST

MUNAZ ENTERPRISES INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 11-4.6.1

ACCESSIBLE PARKING SPACES FOR HANDICAP HAVE NOT BEEN PRO-

VIDED.

FBC 11-4.6.4

THE REQUIRED SIGNAGE FOR HANDICAP ACCESSIBLE PARKING HAS NOT

BEEN PROVIDED.

FBC 11-4.7

THE REQUIRED RAMPS FOR HANDICAP ACCESSIBLE PARKING HAVE NOT

BEEN PROVIDED.

CASE NO: CE03041128

CASE ADDR: 4950 W PROSPECT RD OWNER: FRYD, ISAAC TR INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF OFFICE PARTITIONS
- B. INSTALLATION OF ACOUSTICAL CEILINGS
- C. INSTALLATION OF STOREFRONT BEHIND ROLL-UP DOOR
- D. INSTALLATION OF SOUND STUDIOS
- E. INSTALLATION OF RECEPTION AREA

#### CODE ENFORCEMENT BOARD

# CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

# F. DEMOLITION OF EXISTING PARTITIONS

#### FBC 104.2.4

THERE HAVE BEEN RENOVATION, RELOCATION AND NEW INSTALLATION OF PLUMBING ITEMS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS. THESE ITEMS INCLUDE, BUT ARE NOT LIMITED TO:

A. REMOVAL OF PLUMBING CONNECTIONS AND CAPPING OF TIE-IN LINES.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES, BUT IS NOT LIMITED TO:

- A. INTERIOR SERVICE SUB-PANEL HAS INCORRECT COVER
- B. STAGE LIGHTING INSTALLED
- C. NUMEROUS WIRES AND CORDS EXPOSED AND NOT PROPERLY SECURED.
- D. WIRING AND TERMINATIONS CAPPED
- E. INTERIOR WALL OUTLETS NOT PER PLAN

# FBC 11-4.6.1

ACCESSIBLE PARKING SPACES FOR HANDICAP HAVE NOT BEEN PROVIDED.

#### FBC 11-4.6.4

THE REQUIRED SIGNAGE FOR HANDICAP ACCESSIBLE PARKING HAS NOT BEEN PROVIDED.

#### FBC 11-4.7

THE REQUIRED RAMPS FOR HANDICAP ACCESSIBLE PARKING HAVE NOT BEEN PROVIDED.

# FBC 1016.3.1

EMERGENCY EXIT SIGNS REQUIRED.

#### 15-28

OCCUPATIONAL LICENSE REQUIRED. BUSINESS IS CURRENTLY OPERATING WITHOUT THE PROPER LICENSES.

# FBC 1016.2.1

EMERGENCY LIGHTING REQUIRED.

### FBC 704.2.3.1

ONE (1) HOUR FIRE SEPARATION IS REQUIRED BETWEEN TENANTS.

\_\_\_\_\_

CASE NO: CE03041145
CASE ADDR: 1139 NW 5 AV
OWNER: HANNON, CHERYL R
INSPECTOR: DOUGLAS KURTOCK

#### VIOLATIONS: FBC 104.2.11

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

A. INSTALLATION OF AIR CONDITIONING UNITS AND EQUIPMENT

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATED AND EXPOSED WIRING AND ELECTRICAL EQUIPMENT.

CE03041988 CASE NO:

CASE ADDR: 1441 N ANDREWS AV OWNER: REES, GEORGE & JANICE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF REPLACEMENT DOORS
- INSTALLATION OF KITCHEN CABINETS
- INSTALLATION OF PORCH RAILINGS AND FENCING
- D. INSTALLATION OF POOL DECKING

#### FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING WINDOW/WALL UNITS AND DRYER VENTS WERE INSTALLED WITHOUT FIRST OBTAINING THE RE-QUIRED PERMITS.

#### FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE EXTERIOR PLUMBING AND WATER FILTRATION SYSTEM AND INTERIOR SINK AND HOT WATER HEATER CONNECTIONS AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO THE NEW HOT WATER HEATER, LIGHT FIXTURES, POOL EQUIPMENT AND MAIN SERVICE PANEL.

CASE NO: CE03050364 CASE ADDR: 1544 NW 4 AV OWNER: WOLFE, RICK INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF NEW REPLACEMENT WINDOWS
- B. INSTALLATION OF WOOD FENCE.

#### FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING UNIT WAS INSTALLED

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03050452 CASE ADDR: 1107 NW 4 AV OWNER: SMITH, GUY D INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF NEW DOORS AND REPLACEMENT WINDOWS
- B. INSTALLATION OF KITCHEN CABINETS
- C. INSTALLATION OF DRYWALL FINISHES AND TEXTURES
- D. INSTALLATION OF ROOF

#### FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND DRAINLINES WITHOUT FIRST OBTAINING THE RE-QUIRED PERMITS.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO THE NEW AIR CONDITIONING UNIT, HOT WATER HEATER AND MAIN SERVICE.

#### FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03050453
CASE ADDR: 1129 NW 7 TER STIMPSON, EVA M OWNER . INSPECTOR: DOUGLAS KURTOCK

#### VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF NEW DOORS AND REPLACEMENT WINDOWS
- B. INSTALLATION OF KITCHEN CABINETS
- C. INSTALLATION OF DRYWALL FINISHES AND TEXTURES
- D. INSTALLATION OF ROOF

# FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

# FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND DRAINLINES WITHOUT FIRST OBTAINING THE RE-

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JULY 22, 2003

10:00AM

QUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO THE NEW AIR CONDITIONING UNIT, HOT WATER HEATER AND MAIN SERVICE.

FBC 3401.6

\_\_\_\_\_\_

CASE NO: CE03050697
CASE ADDR: 1118 NW 19 ST
OWNER: RODRIGUEZ,MARIA D
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED

TO:

A. INSTALLATION OF CONCRETE DRIVEWAY AND PARKING AREA

-----

CASE NO: CE03050858 CASE ADDR: 6700 NW 9 AVE

OWNER: SILVERI LEASING INC INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: 9-305(b)

MINIMUM STANDARD FOR LAWN & LANDSCAPE AREAS. THE LAND-SCAPING IS IN DISREPAIR. GRASS MISSING AND SPRINKLER IRRIGATION NOT WORKING.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF INTERIOR WAREHOUSE OFFICES

FBC 11-4.6.1

ACCESSIBLE PARKING SPACES FOR HANDICAP HAVE NOT BEEN PROVIDED.

FBC 11-4.6.4

THE REQUIRED SIGNAGE FOR HANDICAP ACCESSIBLE PARKING HAS NOT BEEN PROVIDED.

FBC 11-4.7

THE REQUIRED RAMPS FOR HANDICAP ACCESSIBLE PARKING HAVE NOT BEEN PROVIDED.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03050863 CASE ADDR: 1332 NW 5 AV

OWNER: CONSECO FINANCES SERVICING CORP INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF CONCRETE DRIVEWAY AND PARKING AREA

CE03050963 CASE NO: CASE ADDR: 1810 NW 9 ST

RKH INVESTMENTS INC OWNER: INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF KITCHEN CABINETS AND FIXTURES

B. DEMOLITION OF INTERIOR UNITS

CASE NO: CE03051780 CASE ADDR: 1601 NW 2 AV OWNER: GRUNWALD, KURT R INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS, THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF REPLACEMENT DOORS B. INSTALLATION OF REPLACEMENT WINDOWS

C. INSTALLATION OF KITCHEN CABINETS

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

#### CODE ENFORCEMENT BOARD

#### CITY COMMISSION MEETING ROOM - CITY HALL

JULY 22, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03052245
CASE ADDR: 1613 NW 6 AV
OWNER: YOHANNA, AUDREY
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF REPLACEMENT DOORS

- B. INSTALLATION OF REPLACEMENT WINDOWS
- C. INSTALLATION OF KITCHEN CABINETS
- D. INSTALLATION OF ROOF

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

\_\_\_\_\_

CASE NO: CE03061588
CASE ADDR: 721 NE 5 TER
OWNER: WATERMAN, EDMUND
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF ASPHALT PAVED PARKING LOT

18-27(a)

GRASS/PLANT OVERGROWTH, RUBBISH, TRASH AND DEBRIS ON PROPERTY AND/OR SWALE.

47-21.8

GROUND OR LAWN COVER MISSING.

9-306

STRUCTURE NOT BEING MAINTAINED.